

RTI REQUEST DETAILS

Registration No. : CPPRI/R/E/20/00003 **Date of Receipt :** 23/06/2020

Type of Receipt : Online Receipt **Language of Request :** English

Name : Pankaj Kumar Goley **Gender :** Male

Address : CPPRI, Paper Mill Road ,Himmat Nagar, Paper Mill road,
SAHARANPUR. Pin:247001

State : Uttar Pradesh **Country :** India

Phone No. : Details not provided **Mobile No. :** +91-8439485543

Email : pkgoley@gmail.com

Status(Rural/Urban) : Urban **Education Status :** Graduate

Is Requester Below Poverty Line ? : No **Citizenship Status :** Indian

Amount Paid : 10) **Mode of Payment :** Payment Gateway

Does it concern the life or Liberty of a Person ? : No(Normal) **Request Pertains to :** Anuradha V Janbade

With respect to the burning incident of an Air Conditioner that took place on 26/08/2019 in paper testing division of CPPRI, please provide the following information under RTI Act 2005:

Information Sought :

1. Date on which the committee was constituted to probe the above said burning incident.
2. Date on which the above constituted committee commenced the probe.
3. Date on which the above constituted committee submitted its proceedings of probe
4. Name of the chairman and members of the committee constituted to probe the above said burning incident
5. Name of committee member who is electrical expert for carrying out the above probe
6. Copy of proceedings submitted against the above probe by the committee which was constituted to probe the above said burning incident.
7. Copy of Installation report of the above said Air Conditioner
8. Copy of maintenance record of the above said Air Conditioner since the date of its installation
9. Name of all the Heads/Controlling Officers/Incharge of Engineering & Maintenance Division (along with their duration in the Engineering & Maintenance Division) from the date of installation till the date of burning of the above said Air Conditioner
10. Name of the Heads/Controlling Officers/Incharge and Scientific Staff of Paper Testing Division of CPPRI at the time when the burning incident of the above said Air Conditioner took place
11. Copy of report submitted by Electric Inspector who carried out the inspection of the burnt Air Conditioner

Print

Save

Close